Division of Waste Management
UST Section
Civil Penalty Assessments
May 2012

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
Furr Transport LLC PO Box 786 Denton, NC	Bill's Truck Stop 1210 Snider-Kines Rd. Linwood, NC Davidson Co.	Violation of NCGS 143-215.94U by placing petroleum product into UST systems for which the owner or operator did not hold a valid operating permit.	$1,732.04	5/5/12
Eagle Transport Corporation 300 S. Wesleyan Blvd. Rocky Mount, NC	N A Minute Shoppe 1727 NC Hwy 39 S. Henderson, NC Vance Co.	Violation of NCGS 143-215.94U by placing petroleum product into UST systems for which the owner or operator did not hold a valid operating permit.	$3,846.05	5/5/12
Virendra & Vinaben Sethiya 33 Holly Springs Rd. Greensboro, NC	Shumaker's Grocery 1603 Lee's Chapel Rd. Greensboro, NC Guilford Co.	Violation of 15A NCAC 2N .0303 by failing to update registration information for two UST systems and violation of 15A NCAC 2N .0801 by failing to permanently close two substandard UST systems.	$10,617.38	5/18/12
Peddlers Village Group, Inc. 168 Clay Durett Rd. Murphy, NC	Peddlers Village 7251 Hwy 64 W. Murphy, NC Cherokee Co.	Violation of 15A NCAC 2N .0304 by failing to provide secondary containment for six UST systems located 100 to 500 feet of a well serving a public water supply system; violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for six USTs; violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for five pressurized piping systems and one suction piping system; and violation of 15A NCAC 2N .0505 by failing to conduct an annual test of the operation of ALLDs associated with five pressurized piping systems.	$12,794.19	5/3/12
H.D. Oxendine 2440 W. 5th St. Lumberton, NC	Dobbs Place Exxon 2802 W. 5th St. Lumberton, NC Robeson Co.	Violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for three USTs and three pressurized piping systems.	$3,728.38	5/18/12