Division of Waste Management UST Section Civil Penalty Assessments February 2012

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
Priest Grading Company, Inc. 618 Glenwood Rd. Asheboro, NC	Priest Grading Company, Inc. 4135 Us Hwy 64 E Asheboro, NC Randolph Co.	Violation of 15A NCAC 2N .0501, .0502, .0504 and .0506 by failing to comply with leak detection requirements for one UST; violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for one suction piping system; violation of 15A NCAC 2N .0601 and .0603 by failing to report and investigate a suspected release; and violation of 15A NCAC 2N .0801 by failing to secure and maintain a temporarily closed UST system.	\$9,453.39	2/16/12
Royal Mini Mart, LLC 6200 Big Sandy Dr. Raleigh, NC	Royal Mini Mart 3819 Hwy 401 S. Louisburg, NC Franklin Co.	Violation of 15A NCAC 2N .0402 by failing to operate and maintain a corrosion protection system to provide continuous corrosion protection for three UST systems; violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for one UST and three pressurized piping systems; and violation of 15A NCAC 2N .0505 by failing to conduct an annual test of the operation of three automatic line leak detectors on three pressurized piping systems.	\$11,020.30	2/10/12
Greystone Variety Mart, LLC 1492 Warrenton Rd. Henderson, NC	Greystone Variety Mart, LLC 1492 Warrenton Rd. Henderson, NC Vance Co.	Violation of 15A NCAC 2N .0302 by failing to comply with spill prevention requirements for three USTs; violation of 15A NCAC 2N .0304 by failing to provide secondary containment for three UST systems located between 100 and 500 feet of a well serving a public water system; violation of 15A NCAC 2N .0402 by failing to have an impressed current cathodic protection system evaluated by a qualified corrosion protection tester every three years and by failing to inspect an impressed current cathodic protection system every 60 days; and violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for one UST.	\$11,444.38	2/9/12
Southport Waterfront Properties, LLC 6752 Gordon Rd. Wilmington, NC	American Fish Company 319 W. Bay St. Southport, NC Brunswick Co.	Violation of 15A NCAC 2L .0110, .0111 and .0407 by failing to submit a Monitoring report.	\$3,666.16	2/27/12